

..... 1

Cause 1

Solution 1

Gantry

x Gantry

- Position Monitor
 - "F.Position.PreCorrection"
 - "C.Position.PreCorrection"
 - "F.Position.PreCorrection"
 - Position Count "C.Count.PreCorrection", "F.Count.PreCorrection"

"C.Position.PreCorrection",
 Command Position
 Feedback Position
 "C.Count.PreCorrection",

Position Monitor

Reset	C. Position		F. Speed	Torque
Axis 0	200 000	<input checked="" type="checkbox"/> C.Position <input type="checkbox"/> F.Position <input type="checkbox"/> C.Count <input type="checkbox"/> F.Count	0	- 8.70
Axis 1	200 000	<input checked="" type="checkbox"/> C.Speed <input checked="" type="checkbox"/> F.Speed <input checked="" type="checkbox"/> Torque	0	8.90
Axis 2	0	<input type="checkbox"/> C.Position.Motor <input type="checkbox"/> F.Position.Motor <input checked="" type="checkbox"/> C.Position.PreCorrection <input type="checkbox"/> F.Position.PreCorrection <input type="checkbox"/> C.Count.Motor <input type="checkbox"/> F.Count.Motor <input type="checkbox"/> C.Count.PreCorrection <input type="checkbox"/> F.Count.PreCorrection	- 2	0.00

Cause

Solution

Category

From:

<https://www.comizoa.com/info/> - -

Permanent link:

https://www.comizoa.com/info/doku.php?id=application:comiide:tool:gantry:gantry_apply_check&rev=1542951029

Last update: **2024/07/08 18:23**