

10	.....	1
16	.....	2

# Decimal & Hexadecimal

x 10 / 16

10

Category

All

10 16

Load All
 Save All
 Compare To File
 Read All
 Write 1:N
 Write N:N
 EEP All

Load One
 Save One
 Compare To Axis
 Read One
 Write One
 EEP One

Item	Name	Minimum	Maximum	Defalut	Servo	Value	Unit
0	제조사 사용	0	1	1	1	1	---
1	제어 모드 설정	0	6	0	0	0	---
2	실시간 오토튜닝 설정	0	6	1	1	1	---
3	실시간 오토튜닝 기계 강성 설정	0	31	13	14	14	---
4	관성비	0	10000	250	25	25	1%
8	제조사 사용	0	1048576	0	10000	10000	---
9	제조사 사용	0	1073741824	1	1	1	---
10	제조사 사용	1	1073741824	1	1	1	---
11	지원 없음(모터 1회전당 출력 펄스 수)	1	262144	2500	2500	2500	1 Pulse/r
12	지원 없음(펄스 출력 논리 반전)	0	3	0	0	0	---

- 10 Minimum / Maximum / Default / Servo / Value 10

0	10000	250	25	25	1%
0	1048576	0	10000	10000	---
0	1073741824	1	1	1	
1	1073741824	1	1	1	
1	262144	2500	2500	2500	
0	3	0	0	0	
0	500	500	300	300	
0	134217728	100000	10000	10000	
0	2	1	1	1	
0	3	3	3	3	
0	4	0	0	0	
0	30000	480	630	630	
1	32767	270	350	350	
1	10000	210	160	160	
0	5	0	0	0	

KeyPad

10000
←

<<
>>
+/-

1	2	3	OK
4	5	6	
7	8	9	Exit
H	0	.	

- Cell 16
- H 16 KeyPad 가 , 10000 10 , 16

### 16

Category: All

10
16

Load All Save All Compare To File Read All Write 1:N Write N:N EEP All

Load One Save One Compare To Axis Read One Write One

EEP One

Item	Name	Minimum	Maximum	Defalut	Servo	Value	Unit
<input checked="" type="checkbox"/>	0	0x00	0x01	0x01	0x01	0x01	---
<input type="checkbox"/>	1	0x00	0x06	0x00	0x00	0x00	---
<input type="checkbox"/>	2	0x00	0x06	0x01	0x01	0x01	---
<input type="checkbox"/>	3	0x00	0x1F	0x0D	0x0E	0x0E	---
<input type="checkbox"/>	4	0x00	0x2710	0xFA	0x19	0x19	1%
<input type="checkbox"/>	8	0x0000	0x100000	0x0000	0x2710	0x2710	---
<input type="checkbox"/>	9	0x0000	0x40000000	0x0001	0x0001	0x0001	---
<input type="checkbox"/>	10	0x0001	0x40000000	0x0001	0x0001	0x0001	---
<input type="checkbox"/>	11	0x0001	0x40000	0x09C4	0x09C4	0x09C4	1 Pulse/r
<input type="checkbox"/>	12	0x00	0x03	0x00	0x00	0x00	---

• 10

Minimum / Maximum / Default / Servo / Value

16

0x00	0x2710	0xFA	0x19	0x19	1%
0x0000	0x100000	0x0000	0x2710	0x2710	
0x0000	0x40000000	0x0001	0x0001	0x0001	
0x0001	0x40000000	0x0001	0x0001	0x0001	
0x0001	0x40000	0x09C4	0x09C4	0x09C4	
0x00	0x03	0x00	0x00	0x00	

KeyPad

0x2710
←

<<
>>
+/-

1	2	3	OK
4	5	6	
7	8	9	Exit
H	0	.	
A	B	C	Dec
D	E	F	Hex

- Cell 10
- H 16 KeyPad 가 , 0x2710 16 , 10

From:  
<https://www.comizoa.com/info/> - -

Permanent link:  
[https://www.comizoa.com/info/doku.php?id=application:comiide:tool:servotunes:40\\_hexa&rev=1541669068](https://www.comizoa.com/info/doku.php?id=application:comiide:tool:servotunes:40_hexa&rev=1541669068)

Last update: **2024/07/08 18:23**