

ErrorCode : -21086 1
Case 1 1

ErrorCode : -21086

× -21086 Error .

Case 1

- Homing Method 101 -21086 Error
- Touch Probe
- TouchProbe Homing Method

From:

<https://www.comizoa.com/info/> - -

Permanent link:

https://www.comizoa.com/info/doku.php?id=platform:ethercat:100_api:5_errorcode:21086&rev=1587000372

Last update: **2024/07/08 18:22**