

Case 1 ..... 1  
  AddInfo ..... 1  
  Cause ..... 1  
  Solution ..... 1

[ethercat](#), [homing](#), [-21072](#), [touchprobe](#),

# Error : -21086

× -21086 Error

## Case 1

### AddInfo

- Homing Method 101 -21086 Error

### Cause

- Touch Probe

### Solution

- TouchProbe Homing Method

From:  
<https://www.comizoa.com/info/> - -

Permanent link:  
[https://www.comizoa.com/info/doku.php?id=platform:ethercat:100\\_api:5\\_errorcode:21086&rev=1558661647](https://www.comizoa.com/info/doku.php?id=platform:ethercat:100_api:5_errorcode:21086&rev=1558661647)

Last update: **2024/07/08 18:22**