

---

.....	1
<b>Summary</b> .....	1
<b>Part</b> .....	1
<b>UI</b> .....	1
<b>History</b> .....	1
18.10.10 .....	1
18.10.18 .....	1
18.10.19 .....	2
18.10.22 .....	2
18.10.23 .....	2
18.10.24 .....	2

EtherCAT

×

# Introduce

				<b>E-Mail</b>
	SW	( )	010-9199-0391	h2master@nexview.co.kr

# Equipment : LC2000

## Summary

- Laser Cutting System
- Pulse Type COMIZOA EtherCAT
- 
- Motion Controler
- Cutting Sequence Laser Scanner가

## Part

- COMI-LX550
  - : 4 (3 , 1 )
  - 2
- ETS-DI32N-T
- ETS-DO32N-T

## UI

- UI MFC (???) )
- EtherCAT (COSS )
- UI

## History

### 18.10.10

- ( , , )

### 18.10.18

- ( , )
- Config / / IO
-

### 18.10.19

- ( → COSS )

### 18.10.22

- 
- **Gantry**
- SW Update

Item	Details
<b>Firmware</b>	1.69 (app_v1.69_20180918)
<b>Driver</b>	1.5.0.1 (2018-06-19 11:01
<b>Library</b>	1.5.0.1 (2018-09-18 08:46)_x86

### 18.10.23

- 가 ( 7 - )

### 18.10.24

- ( , COSS )
  - InitFormFile, Gantry ( )

From:  
<https://www.comizoa.com/info/> - -

Permanent link:  
<https://www.comizoa.com/info/doku.php?id=work:cooperation:%EB%8B%A4%EC%9B%90%EB%84%A5%EC%8A%A4%EB%B7%B0&rev=1540531098>

Last update: 2024/07/08 18:23